

**Ventura Compressor Station Blowdown Information  
Planned and Unplanned Events**

<b>Date</b>	<b>Amount Vented (MSCF)</b>	<b>Reason</b>	<b>Planned</b>
2015	81.38	Blowdown for maintenance	Y
2016	59.68	Unit Maintenance	Y
3/1/2017 14:28	49.70	ESD	N
4/6/2017 6:56	2.04	Blowdown for maintenance	Y
4/27/2017 8:26	2.28	Blowdown for maintenance	Y
4/27/2017 14:36	6.69	Blowdown for maintenance	Y
5/9/2017 15:06	54.20	ESD	N
5/15/2017 11:58	3.50	Blowdown for maintenance	Y
5/16/2017 7:32	5.02	Blowdown for maintenance	Y
5/19/2017 8:48	3.76	Blowdown for maintenance	Y
5/22/2017 15:34	54.20	ESD	N
5/25/2017 9:52	5.40	Blowdown for maintenance	Y
5/31/2017 8:12	3.77	Blowdown for maintenance	Y
6/15/2017 10:08	3.11	Blowdown for maintenance	Y
7/11/2017 15:30	2.82	Blowdown for maintenance	Y
7/12/2017 14:04	2.17	Blowdown for maintenance	Y
7/13/2017 13:18	2.10	Blowdown for maintenance	Y
7/25/2017 14:36	2.61	Blowdown for maintenance	Y
7/26/2017 12:18	4.75	Blowdown for maintenance	Y
7/27/2017 23:28	56.80	ESD	N
7/31/2017 9:12	4.58	Blowdown for maintenance	Y
7/31/2017 11:42	8.42	Blowdown for maintenance	Y
8/1/2017 8:46	2.33	Blowdown for maintenance	Y
8/1/2017 10:56	3.70	Blowdown for maintenance	Y
8/1/2017 13:24	4.52	Blowdown for maintenance	Y
8/2/2017 0:58	1.96	Blowdown for maintenance	Y
8/17/2017 9:38	3.90	Blowdown for maintenance	Y
8/23/2017 10:36	4.45	Blowdown for maintenance	Y
9/6/2017 9:34	2.20	Blowdown for maintenance	Y
9/20/2017 10:20	3.74	Blowdown for maintenance	Y
10/12/2017 7:56	3.36	Blowdown for maintenance	Y
10/13/2017 8:22	4.56	Blowdown for maintenance	Y
1/3/2018	2.99	Maintenance Blowdown	Y
1/5/2018	2.27	Maintenance Blowdown	Y
1/8/2018	6.63	Maintenance Blowdown	Y
1/11/2018	8.68	Maintenance Blowdown	Y
2/7/2018	2.06	Maintenance Blowdown	Y
2/16/2018	4.18	Maintenance Blowdown	Y
12/7/2018	35.30	Maintenance Blowdown	Y
9/15/2019	107.11	Unplanned ESD	N
7/20/2020	83.00	Planned ESD	Y
7/24/2020	64.00	Planned ESD	Y
7/26/2020	0.06	Overpressure protection device (relief valve) hit setpoint on compressor unit and release gas. Brief release of gas to drop pressure back normal operating levels. Abnormal operating conditions reported and documented.	N
8/3/2020	0.06	Overpressure protection device (relief valve) hit setpoint on compressor unit and release gas. Brief release of gas to drop pressure back normal operating levels. Abnormal operating conditions reported and documented.	N
1/19/2021	46.00	Unplanned ESD	N
7/2/2021 15:43	5.40	Unplanned ESD	N